

BJM CORP ALL-TEST™ Case Study: Dynamometers 012002

- ⇒ Basic Knowledge
- Problem Example
- Improvement Example

Theme: Case Study – Dynamometer at Automotive Plant

Description

Location: Mid-Western Truck Transmission Manufacturing Facility
Dynamometer Motor: 200 Horsepower, Special Motor and Dynamometer Drive, 480 Volts
Effectuated Systems: Final In-Process Inspections, 8% of capacity effected
Failure Cost: >\$125,000 in equipment, not including production, delivery and manpower
Savings: >\$500,000 in equipment, not including production, delivery and manpower

A special dynamometer system failed at a mid-Western truck transmission plant in the final test stage of their process line. The fault damaged over \$125,000 in sensitive drive equipment during production, causing an unplanned outage of 8% of the final test production area.

Initial Readings

The ALL-TEST IV PRO™ 2000 was applied to determine the cause of the fault. The first test was performed at the Motor Control Center (MCC) and indicated a severe short (I/F and Phase Angle) and loose connections (Resistance):

Table 1: Test at MCC

	T1-T2	T1-T3	T2-T3
Resistance	0.013	8.255	8.253
Impedance	7	10	10
Inductance	1	2	2
Phase Angle	62	20	21
I/F	-43	-16	-18
Insulation	>99M		

As per standard practice, the motor was tested at the motor connection box with the following good results:

Table 2: Test at Motor Connection Box

	T1-T2	T1-T3	T2-T3
Resistance	0.034	0.024	0.006
Impedance	8	9	7
Inductance	1	1	1
Phase Angle	64	64	63
I/F	-43	-43	-43
Insulation	>99M		

This indicated that the fault was in the cabling. When inspected, it was found that the connections had been incorrectly crimped causing a loose connection that caused the cable insulation to break down and fail. The fault was a direct short that caused catastrophic damage to the drive. Note that the cable did not ground.

Next Step

Motor Circuit Analysis (MCA) had not been performed on the dynamometer system prior to the cable fault. The system was added to the plant's reliability program and several other dynamometer cables were found to be in the same condition. One dynamometer motor (150 Horsepower) was found to have a coil short:

Table 3: 150 Horsepower Dynamometer at MCC

	T1-T2	T1-T3	T2-T3
Resistance	0.022	0.022	0.022
Impedance	7	7	9
Inductance	1	1	1
Phase Angle	60	62	64
I/F	-43	-43	-42
Insulation	>99M		

The final test stage is very critical, so the Reliability Department added an acceptance test stage to all new and repaired dynamometer motors. An example of a good new 200 Horsepower dynamometer motor test is as follows:

Table 4: 200 Horsepower Dynamometer Acceptance Test

	T1-T2	T1-T3	T2-T3
Resistance	0.012	0.011	0.010
Impedance	8	7	8
Inductance	1	1	1
Phase Angle	64	63	64
I/F	-43	-43	-43
Insulation	>99M		

Cost Avoidance

Early detection and correction of the other faults generated a cost avoidance, in equipment only, of at least \$500,000 should the failures occur the same way as the first 200 horsepower dynamometer. Each dynamometer failure reduces the production capability of the plant by 8% during the final test stage.

Lessons Learned

A review of critical motors in the plant would identify critical equipment that must be included in the reliability program. Motor Circuit Analysis, using the ALL-TEST IV *PRO*TM 2000, can be used to provide incoming inspection, trending analysis and troubleshooting capabilities rare in predictive maintenance equipment. Identification of loose connections, cable faults and winding faults will often provide a very quick simple payback for the program.